

ENGINE LOG BOOK
LYCOMING

Engine Log

Serial # _____

Date	Time Run (Hours)	Total Time Since Overhaul	Repairs, Adjustments, Service, Remarks	Signature	Licence #
BROUGHT FORWARD					

Date: 8/13/24 | N#: N143WY | S/N: CC19-0093 | CUBCRAFTERS

This engine was installed new on aircraft. It has been service with 7 quarts of Aeroshell 100G

CubCrafters Authorized Technician: Nehemiah Losacco Print Name: Nehemiah LOSACCO

CUBCRAFTERS Services 1920 South 16th Ave - Yakima, WA 98903 (KYKM) Phone: (509) 248-1025 Fax: (509) 853-2783

10/22/2024 | Cub Crafters / Lycoming | CC19-215 / IO-390-D3B6 | SN CC19-0093 / SN L-2459-80E | N143WY | EH: 6.8 | TH: 8.3 ETT: 6.8

Drained and serviced engine with 7 quarts of Aeroshell 80 Mineral oil. Retained oil sample for analysis. Inspected removed oil filter. No discrepancies noted. Installed new CH48108-1 oil filter. Aircraft ground run and leak checked. No discrepancies noted. I certify that the work specified above was carried out in accordance with FAA airworthiness regulations and with respect to the work performed; this aircraft is approved for return to service.

Todd Hildebrand A&P 3089718 IA

COASTAL VALLEY Aviation Inc.
(805)928-7701 • www.cvamx.com
ENGINE
DATE: 06/26/2025
N143WY
LYCOMING IO-390-D3B6 SN CC19-0093 TACH: 22.7
1. Changed oil & filter serviced w/6 Qts Aeroshell 80 Mineral
2. Took oil sample for analysis (Owner mailed to Blackstone Labs)

Richard Holder A&P 3340719

COASTAL VALLEY Aviation Inc.
(805)928-7701 • www.cvamx.com
ENGINE
DATE: 09/02/2025
N143WY
LYCOMING IO-390-D3B6 SN L2459-80E TACH: 23.8
1. Compression test IAW Lycoming SI 1191A
#1 76, #2 76, #3 77, #4 75
2. Performed borescope inspection
3. Cleaned, gapped, tested & rotated spark plugs
I certify that this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Richard Holder A&P 3340719 IA

COASTAL VALLEY Aviation Inc.
(805)928-7701 • www.cvamx.com
ENGINE
DATE: 10/02/2026
N143WY
LYCOMING IO-390-D3B6 SN L2459-80E TACH: 47.6
1. Compression test IAW Lycoming SI 1191A
#1 75, #2 76, #3 75, #4 75
2. Performed borescope inspection
3. Cleaned, gapped, tested & rotated spark plugs
4. Changed oil and filter; Serviced w/6qts 20W50 Phillips
5. Took oil sample for analysis & mailed to Blackstone Labs
I certify that this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Richard Holder A&P 3340719 IA

Page Total: _____

Brought Forward: _____

Total to Date: _____

All repair data must bear the endorsement of a certified mechanic, and his/her rating and certificate number MUST be shown.

SSP-1872-1 © 2015 Avco Corporation. All Rights Reserved.