


CC11-00428



*The Standard*

# PROPELLER LOG

ASA-SP-1

**Propeller Record** General Information

Propeller Manufacturer CATTO PROPELLERS

Model CT100/C-80SONLE

Hub Series # \_\_\_\_\_

Date of Manufacture Sept 2018

Type Serial 09186567

Blade # 2

Designed + manufactured  
to comply with  
ASTM F2506-13

**Make/Model**


**Aircraft Installed On:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

2XCARBON COMPOSITE 2B S/N 09186567

DIAMETER 36" PITCH 60" TORQUE 35 FT LBS

CARBON CUB MODEL:

NLE CT100C-80SONLE



ENGINE: CC-340 100HP

DESIGN RPM: 2700

RED LINE RPM MAX: 3100

3/8" BOLTS

MFG DATE: SEPT 2018

7" CRUSH PLATE REQUIRED

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due:	Time Since Overhaul

This Propeller was installed new on serial number CC11-00428

*John Pearson*  
CubCrafters Authorized Technician      06-07-2019 (Date)

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due:	Time Since Overhaul

Registration Number: N30BF      Serial Number: CC11-00428

Dynamically Balanced Propeller ACES Systems.

Weight: Ø    Angle: Ø    IPS: .03

Weight: —    Angle: —    IPS: —

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due:	Time Since Overhaul

*John Pearson*  
Cubcrafters Authorized Technician      06-17-2019 (Date)

Mech. Cert. # or Repair Station # \_\_\_\_\_

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

Year: <b>2019</b> Date: <b>12/16</b>	Total Time in Service	Description
Next Inspection Due:	Time Since Overhaul	<p align="center"> <b>12/16/2019    Catto Propellers    80x50 NLE    SN: 09186567</b>  <b>Tach: 101.4                      Propeller Total Time: 101.4</b> </p>
Year: _____ Date: _____	Total Time in Service	<p align="center"> <b>This propeller has been inspected I.A.W. a 100 hour inspection and was determined to be in airworthy condition.</b> </p>
Next Inspection Due:	Time Since Overhaul	<p align="center"> <b>Jim Stadel A&amp;P 3492117</b>      <i>Jim Stadel</i> </p>
Year: _____ Date: _____	Total Time in Service	
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station # _____


HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

<b>Year:</b> _____	<b>Total Time in Service</b>	<b>Description</b>
<b>Date:</b>		
<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>	
		<b>01/03/2021 Catto Propellers 80x50 NLE SN: 09186567 Tach : 286.0 Propeller Total Time: 286.0</b>
<b>Year:</b> _____	<b>Total Time in Service</b>	<b>I certify that this propeller, spinner and spinner bulkhead have been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.</b>
<b>Date:</b>		
<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>	
		<b>Jim Stadel A&amp;P 3492117</b> <i>Jim Stadel</i>
<b>Year:</b> _____	<b>Total Time in Service</b>	
<b>Date:</b>		
<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>	
		<b>Mech. Cert. # or Repair Station # _____</b>


# HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____	Total Time in Service	<b>Description</b>
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	<p style="text-align: center;"><b>Dec/13/2021 Catto Propellers 80x50 NLE SN: 09186567</b></p> <p style="text-align: center;"><b>Tach: 456.5 Propeller Total Time: 456.5</b></p>
Year: _____	Total Time in Service	<b>Description</b>
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	<p style="text-align: center;"><b>I certify that this propeller, spinner and spinner bulkhead have been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.</b></p> <p style="text-align: center;"><b>Jim Stadel A&amp;P 3492117</b> <i>Jim Stadel</i></p>
Year: _____	Total Time in Service	<b>Description</b>
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	<p style="text-align: center;">Mech. Cert. # or Repair Station # _____</p>

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
Year: _____	Total Time in Service	<p>Jan/10/2023 Catto Propellers 80x50 NLE SN: 09186567 Tach: 621.5 Propeller Total Time: 621.5</p>
Date:		
Next Inspection Due:	Time Since Overhaul	<p>I certify that this propeller, spinner and spinner bulkhead have been inspected in accordance with a 100 hour inspection and were all determined to be in airworthy condition.</p>
Year: _____	Total Time in Service	<p>Jim Stadel A&amp;P 3492117 </p>
Date:		
Next Inspection Due:	Time Since Overhaul	<p>Mech. Cert. # or Repair Station # _____</p>

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

<b>Year:</b> _____ <b>Date:</b> _____	<b>Total Time in Service</b>	<b>Description</b>		
<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>			
<b>Year:</b> _____ <b>Date:</b> _____	<b>Jan/05/2024</b> <b>Tach: 754.4</b>	<b>Catto Propeller</b> <b>Hobbs Time: 972.9</b>	<b>80 X 50 NLE</b>	<b>SN: 09186567</b> <b>Propeller Total Time: 754.4</b>
<b>Next Inspection Due:</b>	I certify that this propeller, spinner and spinner bulkhead have been inspected in accordance with a 100 hour inspection and were determined to be in airworthy condition.			
<b>Year:</b> _____ <b>Date:</b> _____	<b>Jim Stadel</b>	<b>A&amp;P 3492117</b>		
<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>	<b>Mech. Cert. # or Repair Station #</b> _____		

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:		
Year: _____		<p><b>Dec/24/2024      Catto Propeller      80 X 50 NLE      SN: 09186567</b>  <b>Tach: 847.4      Hobbs Time: 1098.6      Propeller Total Time: 847.4</b></p>
Date: _____		
Next Inspection Due:		<p>I certify that this propeller, spinner and spinner bulkhead have been inspected in accordance with a 100 hour inspection and were determined to be in airworthy condition.</p>
Year: _____		<p>Jim Stadel    A&amp;P    3492117      <i>Jim Stadel</i></p>
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

<b>Year:</b> _____	<b>Total Time in Service</b>	<b>Description</b>
<b>Date:</b> _____		

<b>Next Inspection Due:</b>	<b>Jan/06/2025</b>	<b>Catto Propeller</b>	<b>80 X 50 NLE</b>	<b>SN: 09186567</b>
	<b>Tach: 924.3</b>	<b>Hobbs Time: 1205.7</b>	<b>Propeller Total Time: 924.3</b>	

<b>Year:</b> _____	<p>I certify that this propeller, spinner and spinner bulkhead have been inspected in accordance with a 100 hour inspection and were determined to be in airworthy condition.</p>
<b>Date:</b> _____	
<b>Next Inspection Due:</b> _____	
	<p>Jim Stadel    A&amp;P    3492117    <i>Jim Stadel</i></p>

<b>Year:</b> _____	<b>Date:</b> _____	
<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>	
<b>Mech. Cert. # or Repair Station #</b> _____		